

Inspection Report

Manager Review: _____

Date of Inspection: 2/3/2021

Name of Dam: Lake Petit Dam County: Pickens

ID#: _____ Weather: Sunny 45°

Inspected by: Rachel Cochran & Bobby Sauer

Type of Inspection: Bi-Annual Construction Other

Persons Contacted: _____

Toe Drains Right: _____

Toe Drains Left: _____

Additional Drains: _____

Remarks:

1. Overhanging branches along left downstream abutment
Possible seepage along downstream slope - change in grass
coloration also
specifically ~ ~~midway~~ $\frac{3}{4}$ downstream slope
(in line w/ entrance of parking lot
ruts at very bottom before road
multiple Blk corrugated pipes crumbling/deteriorating
seepage along lower left abutment above black pipes
lower pipes have sediment buildup but clear flow
seepage flow behind spillway walls left side
upstream slope bare along left side & various spots
along shore

Lead Inspector